


PACKAGING VIEW




NOTE:


1. NOTE DELETED. 2. LOAD PARTS WITH NOTCH TOWARDS ARROW.

CRITICAL DIMENSION INSPECTION INSTRUCTION TABLE	
ASSEMBLY OPERATION	IN PROCESS INSPECTION
FILL	C1, C2, C3, C4

FIG 3 -TR: TAPE & REEL PACKAGING



UNWINDING DIRECTION → ¬



F:\DWG\MISC\MKTG\SFMX-1XX-XXX-D-XX-MKT.SLDDRW

PROPRIETARY NOTE

THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION AND ALL DESIGN, MANUFACTURING, REPRODUCTION, USE, PATENT RIGHTS AND SALES RIGHTS ARE EXPRESSLY RESERVED BY SAMTEC, INC. THIS DOCUMENT SHALL NOT BE DISCLOSED, IN WHOLE OR PART, TO ANY UNAUTHORIZED PERSON OR ENTITY NOR REPRODUCED, TRANSFERRED OR INCORPORATED IN ANY OTHER PROJECT IN ANY MANNER WITHOUT THE EXPRESS WRITTEN CONSENT OF SAMTEC, INC.

DO NOT SCALE DRAWING

SHEET SCALE: 5:1



PHONE: 812-944-6733 FAX: 812-948-5047 e-Mail: info@SAMTEC.com

.050[1.27] x .050[1.27] LOCKING SOCKET ASSEMBLY

ŜĥMX-1XX-XX-XXX-D-XX

BY: BRATCHER 2/4/99

SHEET 2 OF 2